Kangaroo Joey™

Enteral Feeding & Flush Pump

Loading & Rinsing of Feeding Pump

Proper loading & unloading of a feeding set



1) Feed & flush valve assembly, 2) Feed only valve assembly, 3) Distal end of feeding set, 4) Pump



2) Grasp black ring retainer, gently wrap tubing around rotor, and insert retainer directly into right pocket. Do not overstretch tubing.

Proper rinsing of the feeding set



1) Disconnect feeding set from patient before rinsing. The feeding set must remain loaded during the rinsing procedure.



3) Empty contents of feed bag.



Do not use feeding sets for longer than 24 hours.

1) Grasp thumb tab on valve and insert into left pocket, ensure valve is fully seated. Thumb tab should align with slot in blue door.



3) To properly unload a pump set, power the pump off and wait 10 seconds before removing the feeding set.



2) CAUTION- if set is removed from the pump, it may damage the set and prevent use and will negativley effect the system accuracy.



4) Fill the feed bag with water to approximatley half of the total capacity. Properly seal the bag and shake for 5 to 10 seconds.



5) Empty the feed bag and repeat the last step until the bag contains clean water.



7) Press the "Prime Pump" button to enter the "Prime Pump" screen.



9) Empty bag of water. Prime to remove any remaining water out of the feeding set.



6) Power the pump on. Select "Keep Settings" to continue with previous setting or "Clear Settings" to start with programming new pump settings.



8) Press and hold the "Hold to Prime" button until only clean water flows through the tubing. Once the rotor starts this takes between 1 and 2 minutes.



10) CAUTION- To achieve proper accuracy the fluid level in the feeding set bag must be 6" above the top of the feeding pump, when initiating the feeding cycle.



COVIDIEN, COVIDIEN with Logo and [™] marked brands are trademarks of Covidien AG or an affiliate. © 2008 Covidien AG or ian affiliate. All rights reserved.

H-6211 5M 04/08

15 Hampshire Street Mansfield, MA 02048 800-962-9888 508-261-8000 WWW.COVIDIEN.COM